



Master AD/SI Report

525A - CJ2
S/N 525A-0521 TC-CJA

OWNER:	CEY JET HAVACILIK A.S.	OPERATOR:	SKYLINE TRANSPORTATION AND TRADE CO.
ADDRESS:	AZIZIYE MAH. CINNAH CAD. ANKAYA ANKARA	ADDRESS:	ESENBOGA HAVALIMANI ANKARA
PHONE:		PHONE:	+90 (312) 827 15 62 (EXT:115)
FAX:	+90 312 439 16 98	FAX:	+90 (312) 827 14 06
ANALYST:	TOM THEERLYNCK	+33-1.55.93.47.84 (DIRECT)	PLEASE RECORD CHANGES TO ADDRESS, LAST ACTUALS (IF ANY) AND FAX THIS SHEET BACK TO CAMP.
EMAIL:	TOM.THEERLYNCK@CAMPSYSTEMS.EU	+33 (0) 1.55.93.45.80 (OFFICE) WWW.CAMPSYSTEMS.COM	

Filter Criteria: Task Type In: ('AD','ADP','SB','SBP'); Group by Profile or Bulletin: Profile Type; Mode: With Compliance or Next Due; For: Airframe,Engine,APU Etc;

AIRCRAFT	SERIAL/REGNO: 525A-0521/TC-CJA	MODEL: 525A - CJ2	MANUFACTURER: TEXTRON AVIATION INC.
-----------------	---------------------------------------	--------------------------	--------------------------------------------

DATES		LAST ACTUALS		CURRENT ACTUAL	
CERTIFICATION DATE: 27-SEP-2013		6844:47 A/C HRS	as of 28-FEB-2024	A/C HRS	as of ____/____/____
		6136 AFL	as of 28-FEB-2024	AFL	as of ____/____/____
		2115 ACH	as of 28-FEB-2024	ACH	as of ____/____/____

ENGINE NO. 1	SERIAL/PART: 216449/75000-200	MODEL: FJ44-3A-24	MANUFACTURER: WILLIAMS INTERNATIONAL
---------------------	--------------------------------------	--------------------------	---------------------------------------------

INSTALLED ON 21-JAN-2022		LAST ACTUALS		CURRENT ACTUAL	
4993:25 ENG. HRS	5488:08 A/C HRS	6349:54 ENG. HRS	as of 28-FEB-2024	ENG. HRS	as of ____/____/____
4354 ENC		5693 ENC	as of 28-FEB-2024	ENC	as of ____/____/____

ENGINE NO. 2	SERIAL/PART: 216450/75000-200	MODEL: FJ44-3A-24	MANUFACTURER: WILLIAMS INTERNATIONAL
---------------------	--------------------------------------	--------------------------	---------------------------------------------

INSTALLED ON 21-JAN-2022		LAST ACTUALS		CURRENT ACTUAL	
4993:15 ENG. HRS	5488:08 A/C HRS	6349:54 ENG. HRS	as of 28-FEB-2024	ENG. HRS	as of ____/____/____
4354 ENC		5693 ENC	as of 28-FEB-2024	ENC	as of ____/____/____



Master AD/SI Report

525A - CJ2 S/N 525A-0521 (TC-CJA): 6844:47HRS, 6136 AFL as of 28-Feb-2024

AIRCRAFT

All Bulletins with Compliance or Due
Report Date: 13-Mar-2024

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
AIRFRAME - AD - 525A-0521/TC-CJA							
EASA 2019-0086 R01	FLIGHT CONTROLS – ACTIVE TECHNOLOGY LOAD ALLEVIATING SYSTEM – DEACTIVATION / MODIFICATION - AIRPLANE FLIGHT MANUAL SUPPLEMENT – AMENDMENT					MANDATORY	NOT APPLICABLE - THIS AD IS NOT APPLICABLE SINCE ACTIVE TECHNOLOGY LOAD ALLEVIATING SYSTEM WINGLET IS NOT INSTALLED ON TC-CJA
23-AUG-2019		MOS HRS/MSC - (s) AFL					
EASA 2019-0086 R01 PARA (1)	DEACTIVATE THE ATLAS AND MODIFY THE TACS TO RESTRICT THEIR MOVEMENT, AMEND THE APPLICABLE AFMS, AMEND ITEM 27-60-01 "ATLAS INOPERATIVE" OF THE MMEL SUPPLEMENT TO REMOVE THE 10 FLIGHT HOURS (FH) TIME LIMIT, INFORM ALL FLIGHT CREWS AND, THEREAFTER, OPERATE THE AEROPLANE ACCORDINGLY					MANDATORY	NOT APPLICABLE - THIS AD IS NOT APPLICABLE SINCE ACTIVE TECHNOLOGY LOAD ALLEVIATING SYSTEM WINGLET IS NOT INSTALLED ON TC-CJA.
23-AUG-2019		MOS HRS/MSC DUE (s) AFL					
EASA 2019-0086 R01 PARA (4)	MODIFY THE AEROPLANE IN ACCORDANCE WITH THE INSTRUCTIONS OF SECTION 7 OF THE MODIFICATION SB.					MANDATORY	NOT APPLICABLE - THIS AD IS NOT APPLICABLE SINCE ACTIVE TECHNOLOGY LOAD ALLEVIATING SYSTEM WINGLET IS NOT INSTALLED ON TC-CJA
23-AUG-2019		MOS HRS/MSC 100 (s) AFL					
EASA 2019-0086 R01 PARA (5)	MODIFICATION OF AN AEROPLANE AS REQUIRED BY PARAGRAPH (4) OF THIS AD CONSTITUTES TERMINATING ACTION FOR THE DEACTIVATION, LIMITATIONS AND REPETITIVE PRE-FLIGHT INSPECTIONS AS REQUIRED BY THIS AD FOR THAT AEROPLANE.					MANDATORY	NOT APPLICABLE - THIS AD IS NOT APPLICABLE SINCE ACTIVE TECHNOLOGY LOAD ALLEVIATING SYSTEM WINGLET IS NOT INSTALLED ON TC-CJA
23-AUG-2019		MOS HRS/MSC - (s) AFL					
FAA 2002-20-09	NAVIGATION - COLLINS AFD-3010 AFD UNITS - INSPECT AND MODIFY CERTAIN AFD-3010 AFD UNITS					MANDATORY	NOT APPLICABLE - DUE TO P/N OF DISPLAY INSTALLED
		MOS HRS/MSC A/R AFL		26-SEP-2013 6:24 8			
FAA 2004-08-15	TAWS 8000 TERRAIN AWARENESS					MANDATORY	NOT APPLICABLE - DUE TO PART INSTALLED IN THE AIRCRAFT IS MOD LEVEL C OR HIGHER
		MOS HRS/MSC A/R AFL		26-SEP-2013 6:24 8			
FAA 2005-17-11	PREVENT INCORRECT INSTALLATION OF WIRES TO THE ENGINE FIRE EXTINGUISHER BOTTLES					MANDATORY	NOT APPLICABLE - TO AIRCRAFT SERIAL NUMBER
		DAYS HRS/MSC - AFL		26-SEP-2013 6:24 8			



Master AD/SI Report

525A - CJ2 S/N 525A-0521 (TC-CJA): 6844:47HRS, 6136 AFL as of 28-Feb-2024

AIRCRAFT

All Bulletins with Compliance or Due
Report Date: 13-Mar-2024

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2008-03-10	INSPECT THE LOWER WING SKIN STRUCTURE, FORWARD WING SPAR, LOWER FUSELAGE SKIN, FAIRINGS, AND THE EXTERNAL FAIRING FRAMES FOR CORROSION; REPAIR ANY DAMAGE FOUND; APPLY A CORROSION INHIBITIVE SEALANT TO THE FUSELAGE FAIRINGS BEFORE REINSTALLING; AND DISABLE THE COCKPIT MOUNTED PILOT RELIEF TUBE					AIRWORTHINESS	NOT APPLICABLE - TO AIRCRAFT SERIAL NUMBER
		DAYS		26-SEP-2013			
		HRS/MSC A/R		6:24			
		AFL		8			
FAA 2014-18-01	NAVIGATION - ROCKWELL COLLINS, INC. MODE S TRANSPONDERS - INSPECTION / MODIFICATION					MANDATORY	NOT APPLICABLE - COMPLIED WITH AD2014-18-01 BY LOGBOOK RESEARCH. THIS AD DOES NOT APPLY DUE TO AIRCRAFT SERIAL NUMBER EFFECTIVITY AND THE PART NUMBER OF THE EQUIPMENT INSTALLED. THIS AIRCRAFT HAS PART NO: 622-9210-409 TRANSPONDERS INSTALLED. NO FURTHER ACTION REQUIRED.
		MOS		10-MAR-2016			
		HRS/MSC -		302:30			
		AFL		167			
FAA 2015-08-07	OXYGEN - ZODIAC AEROTECHNICS (FORMERLY INTERTECHNIQUE AIRCRAFT SYSTEMS) FLIGHTCREW OXYGEN MASK REGULATORS - INSPECTION / REPLACEMENT OF INFLATABLE HARNESSSES					MANDATORY	NOT APPLICABLE - COMPLIED WITH AD 2015-08-07 BY VISUAL INSPECTION. BOTH PILOT AND CO-PILOT MASK INSTALLED IN THE AIRCRAFT ARE MANUFACTURED BY BE AEROSPACE. AD 2015-08-07 IS NOT APPLICABLE.
		MOS		03-FEB-2016			
		HRS/MSC -		291:06			
		AFL		161			
FAA 2015-08-07 PARA (G)	INSPECT THE INFLATABLE HARNESS FITTED TO EACH FLIGHTCREW OXYGEN MASK REGULATOR TO DETERMINE IF THE INFLATABLE HARNESS IS INSTALLED WITH A PART NUMBER AND A BATCH NUMBER IDENTIFIED IN APPENDIX I OF ZODIAC AEROSPACE SERVICE BULLETIN MXH-35-240, REVISION 7, DATED SEPTEMBER 1, 2011					MANDATORY	NOT APPLICABLE - COMPLIED WITH AD 2015-08-07 BY VISUAL INSPECTION. BOTH PILOT AND CO-PILOT MASK INSTALLED IN THE AIRCRAFT ARE MANUFACTURED BY BE AEROSPACE. AD 2015-08-07 IS NOT APPLICABLE.
		MOS		03-FEB-2016			
16-JUN-2015		HRS/MSC -		291:06			
		AFL		161			
FAA 2015-08-07 PARA (H)	REPLACE THE INFLATABLE HARNESS IDENTIFIED IN PAPRGRAPH G WITH A NEW OR RE-IDENTIFIED HARNESSSES					MANDATORY	NOT APPLICABLE - COMPLIED WITH AD 2015-08-07 BY VISUAL INSPECTION. BOTH PILOT AND CO-PILOT MASK INSTALLED IN THE AIRCRAFT ARE MANUFACTURED BY BE AEROSPACE. AD 2015-08-07 IS NOT APPLICABLE.
		MOS		03-FEB-2016			
16-JUN-2015		HRS/MSC -		291:06			
		AFL		161			
FAA 2015-10-02	EQUIPMENT/FURNISHINGS - ZODIAC SEATS FRANCE - INSPECTION/REPLACEMENT					MANDATORY	NOT APPLICABLE - COMPLIED WITH AD2015-10-02 BY VISUAL INSPECTION. THIS AD DOES NOT APPLY DUE TO NO ZODIAC SEATS INSTALLED ON THIS AIRCRAFT. NO FURTHER ACTION REQUIRED.
		MOS		10-MAR-2016			
		HRS/MSC -		302:30			
		AFL		167			



Master AD/SI Report

525A - CJ2 S/N 525A-0521 (TC-CJA): 6844:47HRS, 6136 AFL as of 28-Feb-2024

AIRCRAFT

All Bulletins with Compliance or Due
Report Date: 13-Mar-2024

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2015-10-02 PARA (G)	GENERAL VISUAL INSPECTION FOR CRACKING OF SEAT BACKREST LINKS HAVING PART NUMBER (P/N) 90-000200-104-1, P/N 90-000200-104-2, P/N 90-000202-104-1 AND P/N 90-000202-104-2					MANDATORY	NOT APPLICABLE - COMPLIED WITH AD2015-10-02 (G) BY VISUAL INSPECTION. THIS AD DOES NOT APPLY DUE TO NO ZODIAC SEATS INSTALLED ON THIS AIRCRAFT. NO FURTHER ACTION REQUIRED.
12-JUN-2015		MOS HRS/MSC - AFL		10-MAR-2016 302:30 167			
FAA 2015-10-02 PARA (H)	CORRECTIVE ACTIONS - CRACKING IS FOUND ON THE LINK					MANDATORY	NOT APPLICABLE - COMPLIED WITH AD2015-10-02 (H) BY VISUAL INSPECTION. THIS AD DOES NOT APPLY DUE TO NO ZODIAC SEATS INSTALLED ON THIS AIRCRAFT. NO FURTHER ACTION REQUIRED.
12-JUN-2015		MOS HRS/MSC - AFL		10-MAR-2016 302:30 167			
FAA 2015-10-02 PARA (I)	REPLACE ALL SEAT BACKREST LINKS, HAVING P/N 90-000200-104-1, P/N 90-000200-104-2, P/N 90-000202-104-1 AND P/N 90-000202-104-2, WITH NEW LINKS					MANDATORY	NOT APPLICABLE - COMPLIED WITH AD2015-10-02 (I) BY VISUAL INSPECTION. THIS AD DOES NOT APPLY DUE TO NO ZODIAC SEATS INSTALLED ON THIS AIRCRAFT. NO FURTHER ACTION REQUIRED.
12-JUN-2015		MOS HRS/MSC - AFL		10-MAR-2016 302:30 167			
FAA 2015-10-51-E	AVIDYNE INTEGRATED FLIGHT DISPLAY (IFD)- INCORPORATE OPERATIONAL LIMITATIONS INTO LIMITATIONS SECTION OF THE AFM OR AFMS.					MANDATORY	NOT APPLICABLE - COMPLIED WITH AD 2015-10-51- E BY VISUAL INSPECTION. AVIDYNE IFD IS NOT INSTALLED IN THIS ACFT. AD 2015-10-51- IS NOT APPLICABLE ON THIS ACFT.
		MOS HRS/MSC - AFL		03-FEB-2016 291:06 161			
FAA 2015-23-09	OXYGEN - ZODIAC AEROTECHNICS (FORMERLY INTERTECHNIQUE AIRCRAFT SYSTEMS) FLIGHT CREW OXYGEN MASK REGULATORS - INSPECTION / REPLACEMENT OF OXYGEN MASK REGULATORS					MANDATORY	NOT APPLICABLE - COMPLIED WITH AD 2015-23-09 BY VISUAL INSPECTION. BOTH PILOT AND CO-PILOT MASK INSTALLED IN THE AIRCRAFT ARE MANUFACTURED BY BE AEROSPACE. AD 2015-23-09 IS NOT APPLICABLE.
		MOS HRS/MSC - AFL		03-FEB-2016 291:06 161			
FAA 2015-23-09 PARA (G)	INSPECT EACH FLIGHTCREW OXYGEN MASK REGULATOR TO IDENTIFY THE PART NUMBER AND SERIAL NUMBER					MANDATORY	NOT APPLICABLE - COMPLIED WITH AD 2015-23-09 BY VISUAL INSPECTION. BOTH PILOT AND CO-PILOT MASK INSTALLED IN THE AIRCRAFT ARE MANUFACTURED BY BE AEROSPACE. AD 2015-23-09 IS NOT APPLICABLE.
28-DEC-2015		DAYS HRS/MSC - AFL		03-FEB-2016 291:06 161			



Master AD/SI Report

525A - CJ2 S/N 525A-0521 (TC-CJA): 6844:47HRS, 6136 AFL as of 28-Feb-2024

AIRCRAFT

All Bulletins with Compliance or Due
Report Date: 13-Mar-2024

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2015-23-09 PARA (H.1)	REPLACE EACH AFFECTED FLIGHTCREW OXYGEN MASK WITH A PART IDENTIFIED IN PARAGRAPH (H)(1)(I) OR (H)(1)(II).					MANDATORY	NOT APPLICABLE - COMPLIED WITH AD 2015-23-09 BY VISUAL INSPECTION. BOTH PILOT AND CO-PILOT MASK INSTALLED IN THE AIRCRAFT ARE MANUFACTURED BY BE AEROSPACE. AD 2015-23-09 IS NOT APPLICABLE.
28-DEC-2015		DAYS HRS/MSC - AFL		03-FEB-2016 291:06 161			
FAA 2015-23-09 PARA (H.2.I)	REVISE THE EMERGENCY PROCEDURES SECTION OF THE AIRPLANE FLIGHT MANUAL (AFM) BY INSERTING THE STATEMENT PROVIDED IN FIGURE 1					MANDATORY	NOT APPLICABLE - COMPLIED WITH AD 2015-23-09 BY VISUAL INSPECTION. BOTH PILOT AND CO-PILOT MASK INSTALLED IN THE AIRCRAFT ARE MANUFACTURED BY BE AEROSPACE. AD 2015-23-09 IS NOT APPLICABLE.
28-DEC-2015		DAYS HRS/MSC - AFL		03-FEB-2016 291:06 161			
FAA 2015-23-09 PARA (H.2.II)	FABRICATE AND INSTALL A PLACARD ON THE FLIGHTCREW OXYGEN MASK CONTAINER THAT STATES: "USE SELECTOR ON 100% OR EMERGENCY ONLY."					MANDATORY	NOT APPLICABLE - COMPLIED WITH AD 2015-23-09 BY VISUAL INSPECTION. BOTH PILOT AND CO-PILOT MASK INSTALLED IN THE AIRCRAFT ARE MANUFACTURED BY BE AEROSPACE. AD 2015-23-09 IS NOT APPLICABLE.
28-DEC-2015		DAYS HRS/MSC - AFL		03-FEB-2016 291:06 161			
FAA 2015-23-09 PARA (I)	REGULATOR REPLACEMENT					MANDATORY	NOT APPLICABLE - COMPLIED WITH AD 2015-23-09 BY VISUAL INSPECTION. BOTH PILOT AND CO-PILOT MASK INSTALLED IN THE AIRCRAFT ARE MANUFACTURED BY BE AEROSPACE. AD 2015-23-09 IS NOT APPLICABLE.
28-DEC-2015		MOS HRS/MSC - AFL		03-FEB-2016 291:06 161			
FAA 2016-11-20	OXYGEN - INSPECTION AND REPLACEMENT OF B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT (PBE), PART NUMBER 119003-11 THAT ARE INSTALLED ON AIRPLANES. (SUPERSEDED BY FAA AD 2017-18-12)					MANDATORY	NOT APPLICABLE - AD 2016-11-20 DOES NOT APPLY. EQUIPMENT NOT INSTALLED. INCLUDES PARA (G), PARA (H)(1) AND PARA (H)(2).
		MOS HRS/MSC - AFL ACH		23-SEP-2016 365:42 202 193:42			
FAA 2016-11-20 PARA (G)	PHYSICALLY INSPECT THE PBE POUCH TO DETERMINE IF IT HAS AN INTACT VACUUM SEAL IN ACCORDANCE WITH B/E AEROSPACE SERVICE BULLETIN NO. 119003-35-011, REV .000, DATED FEBRUARY 4, 2015, PARA III.A.1 SUPERSEDED BY FAA AD 2017-18-12					MANDATORY	NOT APPLICABLE - AD 2016-11-20 DOES NOT APPLY. EQUIPMENT NOT INSTALLED. INCLUDES PARA (G), PARA (H)(1) AND PARA (H)(2).
15-JUL-2016		MOS HRS/MSC - AFL		23-SEP-2016 365:42 202			



Master AD/SI Report

525A - CJ2 S/N 525A-0521 (TC-CJA): 6844:47HRS, 6136 AFL as of 28-Feb-2024

AIRCRAFT

All Bulletins with Compliance or Due
Report Date: 13-Mar-2024

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2016-11-20 PARA (H.1)	REPLACEMENT OF A PBE POUCH, FOUND DURING THE INSPECTION IN PARAGRAPH (G) OF THIS AD, THAT DOES NOT HAVE AN INTACT VACUUM SEAL. SUPERSEDED BY FAA AD 2017-18-12					MANDATORY	NOT APPLICABLE - AD 2016-11-20 DOES NOT APPLY. EQUIPMENT NOT INSTALLED. INCLUDES PARA (G), PARA (H)(1) AND PARA (H)(2).
15-JUL-2016		MOS HRS/MSC - AFL		23-SEP-2016 365:42 202			
FAA 2016-11-20 PARA (H.2)	REPLACEMENT OF A PBE POUCH, FOUND DURING THE INSPECTION IN PARAGRAPH (G) OF THIS AD, WHERE THE VACUUM SEAL IS INTACT. SUPERSEDED BY FAA AD 2017-18-12					MANDATORY	NOT APPLICABLE - AD 2016-11-20 DOES NOT APPLY. EQUIPMENT NOT INSTALLED. INCLUDES PARA (G), PARA (H)(1) AND PARA (H)(2).
15-JUL-2016		MOS HRS/MSC - AFL		23-SEP-2016 365:42 202			
FAA 2017-16-01	EQUIPMENT / FURNISHINGS - AMERI-KING CORPORATION MODEL AK-450() AND AK-451() SERIES EMERGENCY LOCATOR TRANSMITTERS - REPETITIVE INSPECTIONS, CHECKS, TESTS AND VERIFICATIONS					MANDATORY	NOT APPLICABLE - N/A BY NOT INSTALLED AMERI KING ELT
		MOS HRS/MSC - (s) AFL		28-SEP-2018 1999 1728			
FAA 2017-16-01 PARA (G)	PERFORM GENERAL VISUAL INSPECTIONS OF THE ELT FOR DISCREPANCIES; CHECKS , TESTS AND VERIFICATIONS AS APPLICABLE, TO ENSURE THE ELT IS FUNCTIONING, AND ALL APPLICABLE CORRECTIVE ACTIONS						NOT APPLICABLE - N/A BY NOT INSTALLED AMERI KING ELT
24-OCT-2017		MOS HRS/MSC - AFL		28-SEP-2018 1999 1728			
FAA 2017-16-01 PARA (J)	OPTIONAL TERMINATING ACTION: REPLACE ELT WITH A SERVICEABLE FAA-APPROVED ELT					MANDATORY	NOT APPLICABLE - N/A BY NOT INSTALLED AMERI KING ELT
24-OCT-2017		MOS HRS/MSC - (s) AFL		28-SEP-2018 1999 1728			
FAA 2017-18-12 PARA (I) & (J)	INSPECT TO DETERMINE IF THE S/N OF THE INSTALLED PBE, P/N 119003-21, IS WITHIN THE RANGE OF 004-14768M THROUGH 004-21093M OR 004-02393M THROUGH 004-03033M AND IF FOUND WITHIN THE S/N RANGE REPLACE IT.						NOT APPLICABLE - N/A SINCE PBE IS NOT INSTALLED.
16-OCT-2017		MOS HRS/MSC - AFL					
FAA 2020-10-05	NAVIGATION - ROCKWELL COLLINS PRO LINE 4 AND PRO LINE 21 FLIGHT MANAGEMENT SYSTEMS					MANDATORY	COMPLIED WITH
24-JUN-2020		MOS HRS/MSC - AFL		28-MAY-2021 4853 4233			
FAA 2021-07-13	EQUIPMENT AND FURNISHING - SEAT RESTRAINT SYSTEM PLASTIC ROTARY BUCKLE HANDLE - INSPECTION/REPLACEMENT					MANDATORY	NOT APPLICABLE
		MOS HRS/MSC - AFL		13-APR-2022			
FAA 2021-07-13 PARA (E)(1)	INSPECT THE BUCKLE HANDLE FOR A CRACK AND IF CRACKED, BEFORE FURTHER FLIGHT, REPLACE IT WITH AN AIRWORTHY BUCKLE					MANDATORY	NOT APPLICABLE
11-MAY-2021		MOS HRS/MSC - AFL		13-APR-2022			



Master AD/SI Report

525A - CJ2 S/N 525A-0521 (TC-CJA): 6844:47HRS, 6136 AFL as of 28-Feb-2024

AIRCRAFT

All Bulletins with Compliance or Due
Report Date: 13-Mar-2024

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2021-07-13 PARA (E)(2)	MEASURE THE THICKNESS OF THE BUCKLE HANDLE VANE; IF THICKNESS IS 0.125 INCH OR GREATER, BEFORE FURTHER FLIGHT, REMOVE THE BUCKLE FROM SERVICE AND REPLACE IT WITH AN AIRWORTHY BUCKLE					MANDATORY	NOT APPLICABLE
11-MAY-2021		MOS HRS/MSC - AFL		13-APR-2022			
FAA 2021-07-13 PARA (E)(3)	DO NOT INSTALL A BUCKLE OR RESTRAINT SYSTEM WITH A BUCKLE P/N 1111430 OR 1111475, ALL DASH NUMBERS, WITH A HANDLE VANE THICKNESS OF 0.125 INCH OR GREATER					MANDATORY	NOT APPLICABLE
11-MAY-2021		MOS HRS/MSC - AFL		13-APR-2022			
FAA 2021-23-12	INDICATING / RECORDING / NAVIGATION - RADIO (RADAR) ALTIMETER - AFM REVISION TO INCORPORATE LIMITATIONS					MANDATORY	COMPLIED WITH
		MOS HRS/MSC - AFL		13-APR-2022			



Master AD/SI Report

525A - CJ2 S/N 525A-0521 (TC-CJA): 6844:47HRS, 6136 AFL as of 28-Feb-2024

AIRCRAFT

All Bulletins with Compliance or Due
Report Date: 13-Mar-2024

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
APPLIANCE - 525A-0521/TC-CJA							
EASA 2019-0086-E	APPLIANCE/EMERGENCY AD - FLIGHT CONTROLS - ACTIVE TECHNOLOGY LOAD ALLEVIATING SYSTEM - DEACTIVATION / MODIFICATION - AIRPLANE FLIGHT MANUAL SUPPLEMENT - AMENDMENT					MANDATORY	NOT APPLICABLE - THIS AD IS NOT APPLICABLE SINCE ACTIVE TECHNOLOGY LOAD ALLEVIATING SYSTEM IS NOT INSTALLED ON TC-CJA
19-APR-2019		MOS HRS/MSC - (s) AFL					
EASA 2019-0086-E PARA (1)	DEACTIVATE THE ATLAS AND MODIFY THE TACS TO RESTRICT THEIR MOVEMENT						NOT APPLICABLE - THIS AD IS NOT APPLICABLE SINCE ACTIVE TECHNOLOGY LOAD ALLEVIATING SYSTEM IS NOT INSTALLED ON THE AIRCRAFT (TC-CJA).
19-APR-2019		MOS HRS/MSC - (s) AFL					
EASA 2019-0086-E PARA (4)	CONTACT CRANFIELD AEROSPACE SOLUTIONS FOR APPROVED ATLAS MODIFICATION INSTRUCTIONS AND ACCOMPLISH THOSE INSTRUCTIONS ACCORDINGLY						NOT APPLICABLE - C
19-APR-2019		MOS HRS/MSC - (s) AFL					
EASA 2019-0086-E PARA (5)	MODIFICATION OF AN AEROPLANE AS REQUIRED BY PARAGRAPH (4) OF THIS AD CONSTITUTES TERMINATING ACTION FOR THE DEACTIVATION, LIMITATIONS AND REPETITIVE PRE-FLIGHT INSPECTIONS AS REQUIRED BY THIS AD FOR THAT AEROPLANE					MANDATORY	NOT APPLICABLE - THIS AD IS NOT APPLICABLE SINCE ACTIVE TECHNOL
19-APR-2019		MOS HRS/MSC - (s) AFL					
FAA 2014-17-02	APPLIANCE AD - EMERGENCY LOCATOR TRANSMITTER - BATTERY WIRING DISCREPANCIES - HONEYWELL ASCA INC					MANDATORY	NOT APPLICABLE - COMPLIED WITH BY INSPECTION, AND FOUND NOT APPLICABLE. EQUIPMENT AFFECTED BY THIS AD IS NOT INSTALLED IN THIS AIRCRAFT. PLEASE CLEAR FROM CESCO.
09-SEP-2014		MOS HRS/MSC - (s) AFL		02-OCT-2014 133 82			
FAA 2015-10-51	APPLIANCE AD - AVIDYNE INTEGRATED FLIGHT DISPLAY (IFD)- INCORPORATE OPERATIONAL LIMITATIONS INTO LIMITATIONS SECTION OF THE AFM OR AFMS					MANDATORY	NOT APPLICABLE - COMPLIED WITH AD 2015-10-51- E BY VISUAL INSPECTION. AVIDYNE IFD IS NOT INSTALLED IN THIS ACFT. AD 2015-10-51- IS NOT APPLICABLE ON THIS ACFT.
01-JUL-2015		MOS HRS/MSC - AFL		03-FEB-2016 291:06 161			



Master AD/SI Report

525A - CJ2 S/N 525A-0521 (TC-CJA): 6844:47HRS, 6136 AFL as of 28-Feb-2024

AIRCRAFT

All Bulletins with Compliance or Due
Report Date: 13-Mar-2024

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
AIRFRAME - SB - 525A-0521/TC-CJA							
SB	525A-34-41 R01	NAVIGATION - AUTOMATIC DEPENDENT SURVEILLANCE BROADCAST (ADS-B) OUT TRANSPONDER INSTALLATION, SERVICE BULLETIN				OPTIONAL	COMPLIED WITH - R/H: REMOVED P/N: 622-3219-409 S/N: 4KXXL INSTALLED P/N: 622-9210-501 S/N: 4K092V L/H: REMOVED P/N: 622-9210-409 S/N: 4KXXK INSTALLED P/N: 622-9219-501 S/N: 4KD92T
	20-APR-2018	MOS		30-APR-2020			
		HRS/MSC	-	3665			
		AFL		3182			
SB	CIB-28-01	FIREWALL SHUTOFF VALVE GROUND IMPROVEMENT, SERVICE BULLETIN				RECOMMENDED	COMPLIED WITH - PERFORMED IAW CIB-28-01
		MOS		17-APR-2017			
	29-MAY-2014	HRS/MSC	-	427			
		AFL		238			
		ACH		277			
SL	CIL-26-01 R01	FIRE PROTECTION - FIRE EXTINGUISHER BOTTLE CARTRIDGE GROUND STUD TORQUING, SERVICE LETTER				MANDATORY	NOT APPLICABLE - FOUND N/A SINCE BOTLLE SQUIBS FOR LH&RH ENGINE FIRE EXTINGUISHER ARE MANUFACTURED ON 31 DECEMBER 2017.
		MOS		31-DEC-2017			
	16-JUN-2016	HRS/MSC	-	1559:53			
		AFL		1318			
		ACH		537			
SL	CIL-32-03	NLG UPLOCK ROLLER BRACKET INSPECTION, SERVICE LETTER				RECOMMENDED	COMPLIED WITH - PERFORMED IAW CIL-32-03
		MOS		10-APR-2017			
	12-NOV-2014	HRS/MSC	-	427			
		AFL		238			
		ACH		277			
SL	CIL-35-05	OXYGEN - TRANSMITTAL OF ZODIAC AEROSPACE SB MCF-SBU-35-001, SERVICE LETTER				MANDATORY	NOT APPLICABLE - COMPLIED WITH CIL-35-05 BY VISUAL INSPECTION. BOTH PILOT AND CO-PILOT MASK INSTALLED IN THE AIRCRAFT ARE MANUFACTURED BY BE AEROSPACE. CIL 35-05 IS NOT APPLICABLE.
		DAYS		03-FEB-2016			
	08-JAN-2016	HRS/MSC	-	291:06			
		AFL		161			
SL	CIL-52-03	DOORS - EMERGENCY ESCAPE HATCH INSPECTION, SERVICE LETTER				MANDATORY	COMPLIED WITH
		MOS		28-MAY-2021			
	04-NOV-2020	HRS/MSC	-	4853			
		AFL		4233			
SL	SL525A-29-03	HYDRAULIC POWER - ENGINE DRIVEN HYDRAULIC PUMP VERIFICATION, SERVICE LETTER				RECOMMENDED	COMPLIED WITH - THIS SERVICE BULLETIN IS N/A BY P/N OF HYDRAULIC PUMPS OF BOTH SIDES. THE HYDRAULIC PUMPS P/N FOUND AS 9912062-6
		MOS					
	13-JUN-2017	HRS/MSC	-				
		AFL					



Task No.		Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL	SL525A-34-16	NAVIGATION - DISABLE FMS TEMPERATURE COMPENSATION AND IMPLEMENT AIRPLANE FLIGHT MANUAL (AFM) CHANGES FOR LNAV/VNAV, SERVICE LETTER					MANDATORY	COMPLIED WITH
	07-OCT-2020		MOS		28-MAY-2021			
			HRS/MSC	-	4853			
			AFL		4233			



Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
ENGINE NO. 1 - AD - 216449/75000-200							
LBA D-2022-197	NO. 1 ENGINE - TURBINE ENGINE - HIGH-PRESSURE TURBINE DISK - REPLACEMENT					MANDATORY	NOT APPLICABLE
06-JUL-2022		MOS HRS/MSC - AFL		(EFF)			



Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
ENGINE NO. 2 - AD - 216450/75000-200							
LBA D-2022-197	NO. 2 ENGINE - TURBINE ENGINE - HIGH-PRESSURE TURBINE DISK - REPLACEMENT					MANDATORY	NOT APPLICABLE
06-JUL-2022		MOS		(EFF)			
		HRS/MSC -					
		ENC					



Master AD/SI Report

525A - CJ2 S/N 525A-0521 (TC-CJA): 6844:47HRS, 6136 AFL as of 28-Feb-2024

AIRCRAFT

All Bulletins with Compliance or Due
Report Date: 13-Mar-2024

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
ENGINE NO. 1 - SB - 216449/75000-200							
SB	FJ44-72-133 R01	NO. 1 ENGINE - REPLACE 1ST LP TURBINE NOZZLE, SERVICE BULLETIN				RECOMMENDED	COMPLIED WITH - PREVIOUSLY
	05-FEB-2016	MOS		20-DEC-2021			
		HRS/MSC -		4993:25			
		ENC		4354			
SB	FJ44-72-140 R01	NO. 1 ENGINE - GEARBOX HOUSING ASSEMBLY - INSPECTION, SERVICE BULLETIN				RECOMMENDED	COMPLIED WITH
	23-AUG-2021	MOS		20-DEC-2021			
		HRS/MSC -					
		ENC					
SB	FJ44-77-013 R09	NO. 1 ENGINE - ENGINE INDICATING - FADEC ENGINE HARNESS ASSEMBLY - REWORK, SERVICE BULLETIN				RECOMMENDED	COMPLIED WITH
	17-JAN-2019	MOS		20-DEC-2021			
		HRS/MSC -					
		ENC					
SB	FJ44-79-012 R01	NO. 1 ENGINE - OIL - LUBE OIL COOLER - REWORK OR REPLACE, SERVICE BULLETIN				RECOMMENDED	COMPLIED WITH
	12-APR-2017	MOS		20-DEC-2021			
		HRS/MSC -					
		ENC					
SB	FJ44-79-013 R02	NO. 1 ENGINE - OIL - OIL FILLER CAP ASSEMBLY - REPLACE (SUPERSEDED BY FJ44-79-013 R03), SERVICE BULLETIN				RECOMMENDED	COMPLIED WITH - REPLACED OIL FILLER CAP
	25-AUG-2017	MOS		29-DEC-2017			
		HRS/MSC -		1154			
		ENC		937			
SB	FJ44-79-013 R05	NO. 1 ENGINE - OIL - OIL FILLER CAP ASSEMBLY - REPLACE, SERVICE BULLETIN				RECOMMENDED	COMPLIED WITH - PREVIOUSLY COMPLIED WITH REVISION 2
	06-AUG-2018	MOS		17-OCT-2018			
		HRS/MSC -					
		ENC					
SB	FJ44-79-016 R03	NO. 1 ENGINE - OIL - RELIEF VALVE ASSEMBLY - REPLACE (SUPERSEDED BY FJ44-79-016 R04), SERVICE BULLETIN				RECOMMENDED	COMPLIED WITH - REPLACED IAW FJ44-79-016 R3
	28-APR-2017	MOS		29-MAY-2017			
		HRS/MSC -		579:11			
		ENC		416			
SB	WISB-72-1034 R03	NO. 1 ENGINE - HP TURBINE - RE-IDENTIFY ASSEMBLY AND DISK, SERVICE BULLETIN				MANDATORY	COMPLIED WITH
	02-JUL-2021	MOS		20-DEC-2021			
		HRS/MSC -					
		ENC					
SB	WISB-72-1037 R02	NO. 1 ENGINE - ACCESSORY DRIVE TOWERSHAFT - REPLACE, SERVICE BULLETIN					COMPLIED WITH
	18-MAR-2021	MOS		20-DEC-2021			
		HRS/MSC -					
		ENC					
SB	WISB-72-1041 R02	NO. 1 ENGINE - HEAT EXCHANGER CLAMP ASSEMBLY - REPLACE, SERVICE BULLETIN					COMPLIED WITH
		MOS		20-DEC-2021			
		HRS/MSC -					
		ENC					



Master AD/SI Report

525A - CJ2 S/N 525A-0521 (TC-CJA): 6844:47HRS, 6136 AFL as of 28-Feb-2024

AIRCRAFT

All Bulletins with Compliance or Due
Report Date: 13-Mar-2024

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB WISB-72-1044	NO. 1 ENGINE - ENGINE - BALANCE PISTON - REPLACE, SERVICE BULLETIN						COMPLIED WITH
15-MAR-2021		MOS HRS/MSC - ENC		20-DEC-2021			
SB WISB-73-1008 R03	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - OIL COOLER TO FDU FUEL TUBE - REPLACE, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - PERFORMED
29-JAN-2019		MOS HRS/MSC - ENC		06-FEB-2019 2296 1997			
SB WISB-73-1008 R04	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - OIL COOLER TO FDU FUEL TUBE - REPLACE, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
19-FEB-2019		MOS HRS/MSC - ENC		20-DEC-2021 4993:25 4354			
SB WISB-73-1009 R04	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES - REPLACE, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
05-AUG-2019		MOS HRS/MSC - ENC		20-DEC-2021 4993:25 4354			
SB WISB-74-1000	NO. 1 ENGINE - IGNITION - IGNITER LEAD INSPECTION AND CLAMPING ARRANGEMENT, SERVICE BULLETIN					MANDATORY	COMPLIED WITH - INSPECTED AND INSTALLED NEW CLAMPS
17-AUG-2017		MOS HRS/MSC - ENC		29-DEC-2017 1154 937			
SB WISB-75-1001 R02	NO. 1 ENGINE - AIR - I.P. BLEED VALVE LEVER PIN - REPLACE, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
20-MAY-2021		MOS HRS/MSC - ENC		20-DEC-2021 4993:25 4354			



Master AD/SI Report

525A - CJ2 S/N 525A-0521 (TC-CJA): 6844:47HRS, 6136 AFL as of 28-Feb-2024

AIRCRAFT
All Bulletins with Compliance or Due
Report Date: 13-Mar-2024

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
ENGINE NO. 2 - SB - 216450/75000-200							
SB	FJ44-72-130 R02	NO. 2 ENGINE - HP COMPRESSOR ROTOR - INSPECTION, SERVICE BULLETIN				RECOMMENDED	COMPLIED WITH
	06-FEB-2018	MOS		20-DEC-2021			
		HRS/MSC -		4993:25			
		ENC		4354			
SB	FJ44-72-133 R01	NO. 2 ENGINE - REPLACE 1ST LP TURBINE NOZZLE, SERVICE BULLETIN				RECOMMENDED	COMPLIED WITH - PREVIOUSLY
	05-FEB-2016	MOS		20-DEC-2021			
		HRS/MSC -		4993:25			
		ENC		4354			
SB	FJ44-72-140 R01	NO. 2 ENGINE - GEARBOX HOUSING ASSEMBLY - INSPECTION, SERVICE BULLETIN				RECOMMENDED	COMPLIED WITH
	23-AUG-2021	MOS		20-DEC-2021			
		HRS/MSC -		4993:25			
		ENC		4354			
SB	FJ44-77-013 R09	NO. 2 ENGINE - ENGINE INDICATING - FADEC ENGINE HARNESS ASSEMBLY - REWORK, SERVICE BULLETIN				RECOMMENDED	COMPLIED WITH
	17-JAN-2019	MOS		20-DEC-2021			
		HRS/MSC -		4993:25			
		ENC		4354			
SB	FJ44-79-012 R01	NO. 2 ENGINE - OIL - LUBE OIL COOLER - REWORK OR REPLACE, SERVICE BULLETIN				RECOMMENDED	COMPLIED WITH
	12-APR-2017	MOS		20-DEC-2021			
		HRS/MSC -		4993:25			
		ENC		4354			
SB	FJ44-79-013 R02	NO. 2 ENGINE - OIL - OIL FILLER CAP ASSEMBLY - REPLACE (SUPERSEDED BY FJ44-79-013 R03), SERVICE BULLETIN				RECOMMENDED	COMPLIED WITH - REPLACED OIL FILLER CAP
	25-AUG-2017	MOS		29-DEC-2017			
		HRS/MSC -		1154			
		ENC		937			
SB	FJ44-79-013 R05	NO. 2 ENGINE - OIL - OIL FILLER CAP ASSEMBLY - REPLACE, SERVICE BULLETIN				RECOMMENDED	COMPLIED WITH - PREVIOUSLY COMPLIED WITH REVISION 2
	06-AUG-2018	MOS		17-OCT-2018			
		HRS/MSC -					
		ENC					
SB	FJ44-79-016 R03	NO. 2 ENGINE - OIL - RELIEF VALVE ASSEMBLY - REPLACE (SUPERSEDED BY FJ44-79-016 R04), SERVICE BULLETIN				RECOMMENDED	COMPLIED WITH - REPLACED IAW FJ44-79-016R3
	28-APR-2017	MOS		29-MAY-2017			
		HRS/MSC -		579:11			
		ENC		416			
SB	WISB-72-1034 R03	NO. 2 ENGINE - HP TURBINE - RE-IDENTIFY ASSEMBLY AND DISK, SERVICE BULLETIN				MANDATORY	COMPLIED WITH
	02-JUL-2021	MOS		20-DEC-2021			
		HRS/MSC -		4993:25			
		ENC		4354			
SB	WISB-72-1041 R02	NO. 2 ENGINE - HEAT EXCHANGER CLAMP ASSEMBLY - REPLACE, SERVICE BULLETIN					COMPLIED WITH
		MOS		20-DEC-2021			
		HRS/MSC -		4993:25			
		ENC		4354			



Master AD/SI Report

525A - CJ2 S/N 525A-0521 (TC-CJA): 6844:47HRS, 6136 AFL as of 28-Feb-2024

AIRCRAFT

All Bulletins with Compliance or Due
Report Date: 13-Mar-2024

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB WISB-72-1044	NO. 2 ENGINE - ENGINE - BALANCE PISTON - REPLACE, SERVICE BULLETIN						COMPLIED WITH
15-MAR-2021		MOS HRS/MSC - ENC		20-DEC-2021 4993:25 4354			
SB WISB-73-1008 R02	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - OIL COOLER TO FDU FUEL TUBE - REPLACE, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
06-AUG-2018		MOS HRS/MSC - ENC		20-DEC-2021 4993:25 4354			
SB WISB-73-1008 R03	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - OIL COOLER TO FDU FUEL TUBE - REPLACE, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - PERFORMED
29-JAN-2019		MOS HRS/MSC - ENC		06-FEB-2019 2296 1997			
SB WISB-73-1009 R04	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES - REPLACE, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
05-AUG-2019		MOS HRS/MSC - ENC		20-DEC-2021 4993:25 4354			
SB WISB-74-1000	NO. 2 ENGINE - IGNITION - IGNITER LEAD INSPECTION AND CLAMPING ARRANGEMENT, SERVICE BULLETIN					MANDATORY	COMPLIED WITH - INSPECTED AND INSTALLED NEW CLAMPS
17-AUG-2017		MOS HRS/MSC - ENC		29-DEC-2017 1154 937			
SB WISB-75-1001 R02	NO. 2 ENGINE - AIR - I.P. BLEED VALVE LEVER PIN - REPLACE, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
20-MAY-2021		MOS HRS/MSC - ENC		20-DEC-2021 4993:25 4354			